

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

G91

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5⁷/₁₂ Mer.

Quarter Corner common to Sections

8, and 9

Corner consists of a Cedar Post (~~not~~) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



<u>Orig</u>	<u>BTs</u>		
-------------	------------	--	--

Species Tom Stb Tom Stp

Diameter 10" 10"

Bearing N41°E N67°W

LKs Distance 127 112

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J A Gjelhaug
 (Signature)

9/18/35
 (Date)

Jr Civil Engr
 (Title)

Old B's Cotton No Trees near To
mark set New cedar post 4' x 4" Old
trail cut thru timber N. but now grown
up with brush

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149N R. 26W S. 74 Mer.