

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P 5/31
E 11

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 57h Mer.



Quarter Corner common to Sections
4, and 9

Corner consists of a N Pine Post (~~not~~) in place
State condition Good

Dimensions above ground 60 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J Pine

Diameter 5"

Bearing East

LKs Distance 2 1/2

Do you believe this to be a genuine Land Office Corner? No

If not, why? Old Bts burnt in heavy fire No

Sign of Cor. To be found. Established 1/4

Cor. on St. Line & Equal Dist. To Sec. Cors.


J A Gjelhovg
(Signature)

9/12/35
(Date)

Jr. Civil Engr
(Title)

Corner again.
Esl. Cor. on straight line between Sec.
Cors & at 1/2 Dist between same
Trail running E & W 6 chs No of Cor

Give any further facts which will aid in finding this
0.21 1/2 chains distant.
from which this Corner bears West
side of tree
tree 5 inches diameter, on the West
Metal Location Poster is on a J. Pine



(Make sketch of topography near Corner)

T. 149N R. 26W 5th Mer.