

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P  
3  
36 A

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5<sup>th</sup> Mer.

Quarter Corner common to Sections  
4, and 33

Corner consists of a Aspen Post (~~post~~) in place

State condition Good

Dimensions above ground 48 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>BT</u>	<u>BT</u>		

Species N Pine Slp N Pine Slp

Diameter 10" 10"

Bearing N 30° E S 9 E

LKS Distance 13 8 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

J A Gjelhaug  
(Signature)

9/19/35  
(Date)

Jr Civil ENGR  
(Title)

Found 2 old B.T.s O.K. and old stp that was marked for corner set New Aspin post in open hole of old stump

Corner again.

Give any further facts which will aid in finding this


0.18 chains distant.

from which this Corner bears N 52.0 W

side of Tree

tree 4 inches diameter, on the N.W.

Metal Location Poster is on a Aspin



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 5-74 Mer.