

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E 13
1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.

Section Corner common to Sections
3, 4, 9, and 10

Corner consists of a Birch Post (not) in place
State condition Good

Dimensions above ground 40 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Fence Post

Diameter 5"

Bearing West

LHs Distance 5

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J A Gjølhaug

(Signature)

9/10/35
(Date)

Jr. Civil Engr.
(Title)

Cor 13 Located on W. side of
Rd running N & S. 8 in line with
fence running West
Found post placed by County

Corner again.

Give any further facts which will aid in finding this


.05 chains distant.

from which this Corner bears East

side of Fence Post

5 inches diameter, on the East

Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 4 Mer.