

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.

Quarter Corner common to Sections
15, and 22

Corner consists of a Birch Post ~~stone~~ in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Old B.T. <u>1/4 S</u> <u>22</u>	<u>New B.T.</u> <u>By Co.</u> <u>1/4 S</u> <u>15</u>		
<u>B.T.</u>	<u>B.T.</u>		

Species Maple Sp. Maple Dead

Diameter 6" 6"

Bearing S. 37° E. N. 71° W.

Distance 20 45

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhoug
(Signature)

Jr. Civil Eng.
(Title)

2/3/36
(Date)

Corner again.
Give any further facts which will aid in finding this


0.26 chains distant.

from which this Corner bears N 10 E

side of Trees

tree 4 inches diameter, on the North

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. I. 149 N. R. 26 W. 5th Mer.