

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 26 W. S. 30 Mer.
Quarter Corner common to Sections

25, and 30 R 25 W

Corner consists of a Cedar posts (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Post	0216 B.T. 1/4s 30			
	B.T.			

Species Cedar ASPEN

Diameter 7" 5"

Bearing S. 75° E N. 40° W

Distance 6 54

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

OLD 0216 CEDAR TREE MKD FOR
CORNER IN PLACE

J. A. Grelthong

(Signature)

10/2/35


(Date)

Jr CIVIL ENGR.

(Title)

Corner again.
on the East edge of
cutting in Cedar Swamp

Give any further facts which will aid in finding this
006 chains distant.
from which this Corner bears N 75° W
side of Tree
tree 7 inches diameter, on the West
Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 8 Mer.