

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

~~874-9~~
L-25

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5¹/₄ Mer.

Quarter Corner common to Sections
13, and 18 R 25 W

Corner consists of a 12 Aspen Post (~~rod~~) in place
State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Orig BT</u> <u>1/45</u> <u>13</u>	<u>Placed</u> <u>Post</u>		

Species Tam Birch

Diameter 10" 3"

Bearing N 74° W S 10° W

LKs Distance 17 16 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J A Gjelhaug
(Signature)

Jr Civil Engr
(Title)

10/11/35
(Date)

L-25

Corner again.

Give any further facts which will aid in finding this


0.16 1/2 chains distant.

from which this Corner bears N 10° E

side of Tree

tree 3 inches diameter, on the North

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 74 Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *149N* R. *26W* *5th* Mer.*Quarter* Corner common to Sections, *13*, and *18* *R25W*Corner consists of a *Aspen Post* (~~not~~) in placeState condition *Good!*Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Dr-19BT</i> <i>1/45</i> <i>13</i>
--

<i>Placed</i> <i>Poster</i>

--

--

<i>BT</i>

--

--

--

Species *Tam* *Birch*Diameter *16"* *3"*Bearing *N74°W* *S10°W**LKs* Distance *1.7* *1.6 1/2*Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

J A Gjelhaug

(Signature)

10/11/35

(Date)

Jr Civil Eng

(Title)

Corner again.

Give any further facts which will aid in finding this


0.16 1/2 chains distant.

from which this Corner bears N 10° E

side of Tree

tree 3 inches diameter, on the No

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 149N R. 26W S. 14 Mer.