

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E25  
P

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5<sup>th</sup> Mer.



Section Corner common to Sections  
1, 12, 6, and 7

Corner consists of an Aspen Post (~~not~~) in place  
State condition Good

Dimensions above ground 48 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam Spruce Spruce \_\_\_\_\_

Diameter 2" 4" \_\_\_\_\_

Bearing S45°E S47°15E \_\_\_\_\_

LKS Distance 49 40 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

J. A. Gjelhaug  
(Signature)

9/20/35  
(Date)

Jr Civil Engr  
(Title)

At point of intersection of Rel. from West & North

Corner again.

Give any further facts which will aid in finding this


0.40 chains distant.

from which this Corner bears N47 1/4° W

side of Tree

tree 14 inches diameter, on the West

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 74 Mer.