

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted R-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 27W 5th Mer.

quarter Corner common to Sections
19, and 20

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Spruce

Diameter 6"

Bearing N 280E

Distance 15 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. Adams

(Signature)

H. Adams Asst. Leader

(Title)

CCC

R-3

11/8/34
(Date)

Blank ruled lines for notes.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

1-3

5th

R 27W

T. 149N