

U. S. Department of Agriculture

FOREST SERVICE

J-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 S. 5 Mer.

14 Corner common to Sections
 _____, _____, 7, and 18.

Corner consists of a POST (not) in place

State condition Good.

Dimensions above ground 2' Dia 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S-18			

Species POPULAR

Diameter 7"

Bearing S 3° SW

Distance 22 Links

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

1-23-34
 (Date)

(Signature) C. H. Sherman
 (Title)

J-3

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree 6 inches diameter, on the

Metal Location Poster is on a *FLM*




(Make sketch of topography near Corner)

T. 119 R. 27 Mer. 5

53

Section Corners 4 7-18

T 189 R 189 Mer. 5



Corner is a Post

Height 2'

Dia 4"

Marked 1/2 57

1/2 918

BEARING TREES

Marks 1/2 918 _____

Species Poplar _____

Diameter 7" _____

Bearing 53° 21' _____

Distance _____
District 27 class _____

Metal poster on 6' E line

Remarks: Post in ground

J-3

Date Jan. 23, 1934 Signed Geo. W. Skirman