

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 5th Mer.  
4 Corner common to Sections  
19, and 20

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Spruce \_\_\_\_\_

Diameter 8" \_\_\_\_\_

Bearing N 27° E \_\_\_\_\_

Distance 0.15 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

11/2/34  
(Date)

(Signature)  
Adams  
(Title)

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 ----- chains distant.  
 ----- from which this Corner bears  
 ----- side of  
 ----- tree ----- inches diameter, on the  
 ----- Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 R. 27 Mer. 5th