

Form 874-9—Revised May, 1918  
**U. S. Department of Agriculture**  
**FOREST SERVICE**

----- NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 149 N. R. 27 W. 5th Mer.

sections Corner common to Sections

17, 18, 19, and 20.

Corner consists of a \_\_\_\_\_ (not) in place


State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec 19	S. 17	S 20	S 18
--------	-------	------	------

BT	BT	BT	BT
----	----	----	----

Species Borneo Sp. Sp. ba'

Diameter 9" 9" 5" 6"

Bearing S45W N15E S31E N48W

Distance 43L 51L 37L 63

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


[Signature]  
 (Signature)

11/8/34  
 (Date)

(Title) N-5

Corner again.  
Fines starting at  
Approt. Cornet turning  
Wds x

Metal Location Poster is on a  
tree inches diameter, on the  
side of from which this Corner bears  
chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 27 W. 5th Mer.

Sections Corner common to Sections  
17, 18, 19, and 20.

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE

Bound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec 17	S. 17	S 20	S 18
BT	BT	BT	BT

Species Sp. Pine Sp. Fir Sp. Spruce Wal  
 Diameter \_\_\_\_\_  
 Bearing S 45 W N 15 E S 31 E N 48 W  
 Distance 7 1/2 5 1/4 37 1/2 63

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

*[Handwritten Signature]*  
(Signature)

11/2/34  
(Date)

