

U. S. Department of Agriculture

FOREST SERVICE

E-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 5th Mer.

Corner common to Sections 5 and 8

Corner consists of a Iron post in place


State condition Fairly Sound

Dimensions above ground 2.8 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Birch

Diameter 10" 5"

Bearing S 10° W N 45° E

Distance 17 LKS. 17 LKS.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Bearing trees + post in fair sound condition

Narrison

(Signature)


(Date)

(Title)

E-7

Lined writing area with horizontal dashed lines.

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 149 R. 27 Mer. 5 34

U. S. Department of Agriculture

FOREST SERVICE

E7

*Posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 27W 5th Mer.

Quarter Corner common to Sections

5, and 6

Corner consists of a Tom. post (not) in place


State condition Fairly sound.

Dimensions above ground 28 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Birch

Diameter 10" 5"

Bearing S10°W N45°E

Distance 17 li. 17 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? Bearing trees and post in too good condition.

*H. Polans*

(Signature)

Asst. Leader

8/29/34

(Date)

(Title)

E-7

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)