

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *149* R. *27* *5* Mer.

Section Corner common to Sections
16, 17, 20, and 21

Corner consists of a *Post* (~~not~~) in place

State condition *Good*.

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>S</i>	<i>S</i>	<i>S</i>	<i>S</i>
<i>17</i>	<i>20</i>	<i>21</i>	<i>16</i>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<i>S</i> <i>21</i>	
		<i>B.T.</i>	

Species _____ *B.*

Diameter _____ *8"*

Bearing _____ *S39°E*

Distance _____ *20 Links.*

Do you believe this to be a genuine Land Office Corner? *yes.*

If not, why? _____

L. B. Ames.


(Signature)

1-4-34
(Date)

Surveyor
(Title) *N-9*

Corner again.
 Also shack is 3 chains N.
 of corner and 1 chain East
 of corner.
 corner is at top of high
 Highland.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 27 W 5TH Mer.

SECTION

Corner common to Sections

17, 16, 20, and 21

Corner consists of a SPRUCE POST (not) in place

State condition BASE ROTTEN OFF

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S 17	S 20	S 21	S 16
------	------	------	------

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 17	S 16	S 21	
------	------	------	--

B.T.	B.T.	B.T.	
------	------	------	--

Species BAL BAL BAL

Diameter 8" 10" 11"

Bearing N 60° W N 45° E S 30° E

Distance 2 LINKS 32 LINKS 31 LINKS

Do you believe this to be a genuine Land Office Corner? NO

If not, why? G.L.O. SURVEY RAN IN 1872. B.T.'S AND CORNER POST ARE COMPARATIVELY RECENT

William A. ...

(Signature)


8/13/34
(Date)

(Title) N-9

.....
.....
.....
.....
.....
.....
.....
.....
.....
.....

Corner again.

Give any further facts which will aid in finding this
..... chains distant.
..... from which this Corner bears
..... side of
..... tree inches diameter, on the
..... Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

N-9
1 of 2

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 5th Mer.

Section Corner common to Sections 16, 17, 20, and 21

Corner consists of a POST (stone) in place

State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
17	20	21	16

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 21	
		BT	

Species B

Diameter 8"

Bearing S39°E

Distance 20 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

[Signature]

(Signature)

1-4-34

(Date)


[Signature]

(Title)

N-9

Corner again.
A Log Shack is 3 chains
N of corner and 1 chain East
of corner
Corner is at Top of high
High Land

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted No
 2082

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 27 W 5th Mer.

Section

Corner common to Sections

17, 16, 20, and 21

Corner consists of a Spruce post (not) in place

State condition Base rotted off.

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

Sec. 17	Sec. 20	Sec. 21	Sec. 16
---------	---------	---------	---------

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec. 17	Sec. 16	Sec. 21	Sec.
B. T.	B. T.	B. T.	

Species Bal. Bal. Bal. B

Diameter 8" 10" 11"

Bearing N 60°W N 45°E S 30°E

Distance 8 Links 32 Links 21 Links

Do you believe this to be a genuine Land Office Corner? No.

If not, why? G.L.O. survey ran in 1875.

B.T.'s and corner post are comparatively recent

Harrison Adams
 (Signature)


8/13/34

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 149 N. R. 27 W. 5th Mer.

11-90
2 of 3