

U. S. Department of Agriculture
FOREST SERVICE

A-9

NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 114 N. R. 27 W. 5 1/2 Mer.

SECTION Corner common to Sections
5, 4, 3, and 2

Corner consists of a ASH POINT (~~not~~) in place
State condition BADLY WORN

Dimensions above ground 1 1/2 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T 1/2</u>			
<u>R 2 1/2</u>			
<u>5</u>			
<u>B.T.</u>			

Species 3/4
Diameter 1 1/2
Bearing 150°
Distance 2 1/2

Do you believe this to be a genuine Land Office Corner? NO

If not, why? It is a very old and worn corner
and the monument is not in place

1/27/34
(Date) _____ (Signature) _____

(Title)

A-9

Handwritten notes on ruled lines, mostly illegible.

Corner again

Give any further facts which will aid in finding this


16 LINKS chains distant.

from which this Corner bears WEST

side of

tree 5 inches diameter, on the LINE BETWEEN

Metal Location Poster is on a ASH



(Make sketch of topography near Corner)

T. W. W. R. 27 W. 5 DE Mer.

U. S. Department of Agriculture

FOREST SERVICE

A-9

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 27 W. Mer. 5 1/4

SECTION Corner common to Sections 5, 4, 32, and 33

Corner consists of a ASH BARK (cut) in place

State condition BADLY ROTTEN

Dimensions above ground 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

MARKS ARE			
ILLEGIBLE			

N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T149N
R27W
S5

B.T.

Species P.P.

Diameter 1 1/2

Bearing S 1/2 W

Distance 2 1/2 LINKS

Do you believe this to be a genuine Land Office Corner? NO

If not, why? G.L.D. SURVEY RAN IN 1875. MARKS ARE RECENT

HAMILTON

(Signature)

8/28/24 (Date)

(Title)

A-9



A-9

Corner again.

Give any further facts which will aid in finding this


16 LINES chains distant.

from which this Corner bears WEST

side of

tree 5 inches diameter, on the LINE BETWEEN

Metal Location Poster is on a ASH



(Make sketch of topography near Corner)

T. ANN R. 27 W. Mer.

