

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V13 P

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 27W 5TH Mer.

SECTION Corner common to Sections
27, 28, 33, and 34



Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species BIRCH STUB BIRCH STUB FALLEN ASPEN

Diameter 8" 8" 6"

Bearing S 68° N N 38° W N 40° E

Distance _____

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

J. M. Larson
 (Signature)

Dec 5 1935
 (Date)

Comptroller
 (Title)

Corner again.

Give any further facts which will aid in finding this


39 LINES chains distant.

from which this Corner bears $S 88^{\circ} W$

side of $E 1/4 M$

tree 10 inches diameter, on the $EAS 1/2$

Metal Location Poster is on $1/4 E 1/4 M$



(Make sketch of topography near Corner)

T. 148 N. R. 27 W. 574 Mer. 1-13

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

California NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 149 R. 21 Mer. 5th

Corner common to Sections
27, 28, 33, and 34

Corner consists of a _____ (set) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>markings obliterated</i>			

Species Birch^{STUB} Birch^{STUB} Yellow aspen

Diameter 8" 8" 8"

Bearing S-68°W N-38°W N-40°E

Distance _____

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

 (Signature)

11-13-35
 (Date)

Comptroller
 (Title)

Dotted lines for writing.

Corner again.


Give any further facts which will aid in finding this

from which this Corner bears ~~39~~ chains distant.

side of ~~ALM~~ *58.2 V.*

tree *10* inches diameter, on the *EAST*

Metal Location Poster is on a *FLM*



(Make sketch of topography near Corner)

T. 144 R. 27 Mer. 5

U. S. Department of Agriculture

FOREST SERVICE

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 27 W 5th Mer.

SECTION Corner common to Sections
27, 28, 33, and 34

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

MARKINGS		OBLITERATED	

Species BIRCH SLUB BIRCH SLUB FALLEN
FALLEN
Diameter 8" 8" 8"
Bearing S-68°N N-38°W N-70°E
Distance _____

Do you believe this to be a genuine Land Office Corner? YES
If not, why? _____

J. M. Larson

(Signature)

Dec 5 1935
(Date)

Comptroller
(Title)

Corner again.

Give any further facts which will aid in finding this


39 LINKS ~~observed distant.~~

from which this Corner bears S88°W

side of ELM

tree 10 inches diameter, on the E151

Metal Location Poster is on a ELM



(Make sketch of topography near Corner)

T. 149 N. R. 27 W. 5th Mer.