

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Shippena NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *149N* R. *27W* S. *5th* Mer.

Sec 12 & 14 Corner common to Sections
10, 11, 14, and 15

Corner consists of a _____ (_____) in place

State condition *Peer*

Dimensions above ground *24* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

<i>T149N</i>	<i>T149N</i>	<i>T149N</i>	<i>T149N</i>
<i>R27W</i>	<i>R27W</i>	<i>R27W</i>	<i>R27W</i>
<i>5</i>	<i>5</i>	<i>5</i>	<i>5</i>
<i>10</i>	<i>15</i>	<i>14</i>	<i>11</i>

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>None</i>	<i>None</i>	<i>None</i>	<i>None</i>

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Harold McLaughlin
 (Signature)

(Date)

Sampassman
 (Title)

Corner located on birch & balsam knoll. North from Tamarack & Spruce swamp

Corner again.

Give any further facts which will aid in finding this


13 links ~~links~~ distant.

from which this Corner bears 110° N of E

side of Section Corner

tree 10 inches diameter, on the East

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 179N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 5th Mer.
SECTION Corner common to Sections
10, 11, 17, and 15

Corner consists of a _____ (not) in place
State condition POOR


Dimensions above ground 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

NONE

NONE

NONE

NONE



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Harold McLaughlin
(Signature)

(Date)

(Title)

CORNER & R LOCATED ON BIRCH
+ SPRUCE SWAMP
+ 55 M KNOL. NORTH FROM TOWN

Corner again.
Give any further facts which will aid in finding this
13 LINES chains distant.
from which this Corner bears 110 N. OF E.
side of SECTION CORNER
tree 10 inches diameter, on the N.W. S.
Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 149 R. 21 Mer. 5721

U. S. Department of Agriculture
FOREST SERVICE

517K

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 149N R. 27W 5th Mer.
Section Corner common to Sections
10, 11, 14, and 15

Corner consists of a Post (~~stone~~) in place
State condition Post

Dimensions above ground 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



T149N	T149N	T149N	T149N
R27W	R27W	R27W	R27W
5	5	5	5
10	15	14	11
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None	None	None	None

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Harold McLaughlin
(Signature)

(Date)


Sampass Man
(Title)

J-17

Corner located on birch balsam
Knull North from Tomalak T
SPRINGS B. Swamp

Corner again.
Give any further facts which will aid in finding this

7 Links ~~across~~ distant.
from which this Corner bears N. N. E.
side of Section corner
tree 10 inches diameter, on the East
Metal Location Poster is on a Birch



T. 149N R. 27W S. 14
Mer
(Name sketch of topography near Corner) 5-17