

Form 874-0--Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-17

~~Chippewa~~ ACC. NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 27W 5th Mer.

Section Corner common to Sections  
3, 2, 10, and 11

Corner consists of a post - (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T149N	S	S	S
R27W	10	11	2
Sec 3			
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Obliterated			

Species Birch stump

Diameter 12"

Bearing N 46° W

Distance 13 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Roy Nelson*  
(Signature)

Chief of Party CCC  
(Title)

3/14/35  
(Date)

E-17

Faded text at the top of the page, possibly a header or title area.

Corner again.

Give any further facts which will aid in finding this


0.14 chains distant.

from which this Corner bears S 32° W

side of tree

tree 6 inches diameter, on the

Metal Location Poster is on a Ash



(Make sketch of topography, if any other)

U. S. Department of Agriculture

FOREST SERVICE

E-17

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14<sup>th</sup> R. 27<sup>th</sup> W 5<sup>th</sup> Mer.

Section Corner common to Sections

3, 2, 10, and 11

Corner consists of a Post (~~mark~~) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

T14 <sup>th</sup>	S	5	5
R27 <sup>th</sup> W	10	11	2
53			

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

OBLITERATED			

Species BIRCH STUMP

Diameter 12"

Bearing N 46° W

Distance 131

Do you believe this to be a genuine Land Office Corner? Y

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

3/14/35  
(Date)

Roy Nelson  
(Signature)  
Chief of Party  
(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

~~corner~~ distant.

141

5320W


from which this Corner bears

1/4

side of

tree 6" inches diameter, on the NE

Metal Location Poster is on a Ash



(Make sketch of topography near Corner)

T. L. HAN R. 27W 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

E-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27 5th Mer.

See Corner common to Sections  
3, 2, 10, and 11

Corner consists of a Post (not) in place

State condition Rattled off

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

T-149N	R-27W		
53	52	510	511

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<del>T-149N</del>
R-27W

T-149N
R-27W

—
---

--

BT
----

BT
----

BT
----

--

Species Bir Bir Basswood

Diameter 14" Badly decayed

Bearing N°E

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Hanks

(Signature)

4/20/34

(Date)

T.F. F36

(Title)

E-17

Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.

		Sec.		
		Sec.		
		Sec.		
		Sec.		

(Make sketch of topography near Corner)