

U. S. Department of Agriculture  
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 5TH Mer.

SECTION

Corner common to Sections

14, 13, 12, and 25

Corner consists of a BIRCH (not) in place

State condition GOOD

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	S	S
14	13	12	24

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S	
23	


S	
24	


B.T.	
------	--

--	--

B.T.	
------	--

--	--

Species BIRCH BIRCH ASPEN

Diameter 1" 8" 1 1/4"

Bearing S 14° W S 76° E S 78°

Distance 24 LINKS 20 LINKS 30 LINKS

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Hamilton Adams

(Signature)

1-17-35

(Date)

Asst. Leader

(Title)

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

C. H. S. W. 329. NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 27 W. S. Th. Mer.

SECTION Corner common to Sections

14, 13, 23, and 24

Corner consists of a WOOD POST (not) in place


State condition ROTTEN

Dimensions above ground 25" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? NO B.T.'S present

Herriam Adams  
(Signature)


Asst. Leader  
(Title)

12/4/34  
(Date)

N-21  
1-22

Section Corners 11, 13, 23, 24

T 11 R 27 Mer. S



Corner is  
a Post

Height 5'

Dia 1 1/2"

Marked SEES

11-13-23-24

BEARING TREES

Marks	<u>S 14</u>	<u>S 13</u>	<u>23</u>	<u>24</u>
Species	<u>Poplar</u>	<u>Poplar</u>	<u>23</u>	<u>24</u>
Diameter	<u>12"</u>	<u>15"</u>	<u>3'</u>	<u>4'</u>
Bearing	<u>N60°E</u>	<u>S75°E</u>	<u>72°E</u>	<u>81°W</u>
District	<u>25</u>	<u>25</u>	<u>25</u>	<u>25 LINKS</u>

Metal poster on SW 1/4 Sec. 24

Remarks:

N-21

Date Feb. 8, 1934 Signed John W. ...

U. S. Department of Agriculture

FOREST SERVICE

Chippewa Acq. NATIONAL FOREST

N-21  
2012

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 27 W. 5th Mer.

Section Corner common to Sections  
14, 13, 22, and 24

Corner consists of a Birch post (not) in place  
State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S-14		S-23	
	S-13		S-24

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-23		S-24	Illegible
B. T.			

Species Birch Birch Aspen  
Diameter 6" 8" 14"  
Bearing S14°W S76°E S 78°  
Distance 24 li. 23 li. 30 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Harrison Adams

(Signature)

1/17/35


(Date)

Asst. Leader, CCC

(Title)

N-21

Metal Location Poster is on a Birch tree . . . . . ft. inches diameter, on the side of . . . . . from which this Corner bears N 76° W 0.23 chains distant. Give any further facts which will aid in finding this Corner again.



T 149 N R. 27 W 5th Mer. (Make sketch of topography near Corner)

*Handwritten notes:*  
 2 of 3  
 N 26