

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 27426 5 Mer.

See. Corner common to Sections

19, 30, 24, and 25

Corner consists of a Post (not) in place

State condition 2" x 2" x 24"

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

30			
----	--	--	--

B.T			
-----	--	--	--

Species pine str.

Diameter 8"

Bearing S 22° E

Distance 16 links.

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

L. G. J.

(Signature)

2-8-34

(Date)

(Title)

R-25

Post-hat in place

Corner again.

Give any further facts which will aid in finding this


11 YRS. ~~days~~ distant.

from which this Corner bears N 5° W

side of

tree 8" inches diameter, on the

Metal Location Poster is on a Elm



(Make sketch of topography near Corner)

T 149 R 27 Mer. 5

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Shipman NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *149* R. *27* *5th* Mer.

Sec Corner common to Sections
24, 19, 25, and *30*

Corner consists of a *corner post (not)* in place

State condition *replaced*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>S</i>	<i>all other markings</i>		
<i>obliterated</i>			

Species *Stub, badly decayed*

Diameter *1.0 in*

Bearing *S. 18° 30' E.*


Distance *7 links*

Do you believe this to be a genuine Land Office Corner? *ye*

If not, why? _____

J. M. Larsen
(Signature)
Dec. 19-35 *Comptroller*
(Date) (Title)
R-25

Metal Location Poster is on a *corner*
 tree *5* inches diameter, on the *N. E.*
 side of *the former corner*
 from which this Corner bears *N. 31° 30' W.*
~~20 miles or more~~ distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)