

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

V-19

NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 14 R. 28 S. 5 Mer.

Corner common to Sections 26, and 35

Corner consists of a TAM POST (not) in place  
 State condition fair

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>S</u>		<u>S</u>	
<u>26</u>		<u>35</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>		<u>1/4</u>	
<u>S</u>		<u>S</u>	
<u>26</u>		<u>35</u>	
<u>BT</u>		<u>BT</u>	

Species SPRUCE TAM  
 Diameter 4" 4"  
 Bearing 125° N 207° S of E  
 Distance 14 feet 8 feet

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

Smith  
 (Signature)

1-27-36  
 (Date)

W. J. ...  
 (Title)

V-19

Corner again.

Give any further facts which will aid in finding this

corner distant.

from which this Corner bears


127  
Bearing 20 S. 04. E

side of

tree 4 inches diameter, on the NW-Side

Metal Location Poster is on a

TAM



(Make sketch of topography near Corner)

Mer.

5

R. 28

T. 149

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

V-19

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5th Mer.

1/4 Corner common to Sections 26, and 35

Corner consists of a Turn Post (not) in place

State condition Fair

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 5 26		1/4 5 35	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 5 26		1/4 5 35	
BT		BT	

Species Spruce Turn.

Diameter 4" 4"

Bearing 10° E. of N 20° S. of E

Distance 14 ft. 8 ft.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Smith  
(Signature)

Compassman  
(Title)

1/27/36  
(Date)

V-19

Corner again.

Give any further facts which will aid in finding this


12 lbs chains distant.

from which this Corner bears 20° S of E

side of Bearing tree

tree 4 inches diameter, on the NW side

Metal Location Poster is on a Tam.



(Make sketch of topography near Corner)

T. 149 N. R. 28 W. 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

P 5/36  
V19

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5th Mer.

1/4 Corner common to Sections  
26, and 35

Corner consists of a Tam. Post (not) in place  
State condition Fair

Dimensions above ground 2 1/4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u> <u>S</u> <u>26</u>		<u>1/4</u> <u>S</u> <u>35</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S</u> <u>26</u>		<u>1/4</u> <u>S</u> <u>35</u>	
<u>BT</u>		<u>BT</u>	

Species Spruce Tam.

Diameter 4" 4"

Bearing 10° E of N 20° S of E

Distance 14 ft. 8 ft.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Smith

(Signature)

Compassman

(Title)

1/27/36  
(Date)

Corner again.


Give any further facts which will aid in finding this

12 1/2 miles distant.

from which this Corner bears 20.5 of E

side of Bearing tree  
tree 4 inches diameter, on the NW side

Metal Location Poster is on a Tam.



(Make sketch of topography near Corner)

T. 141 N. R. 28 W. 5th Mer.