

U. S. Department of Agriculture  
FOREST SERVICE

*Handwritten:* 21  
22

~~Chippewa~~ ~~Acq.~~ NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 5th Mer.  
.....  
..... section ..... Corner common to Sections  
23 , 24 , 26 , and 25

Corner consists of a wood post (not) in place  
State condition (post on ground) poor.

Dimensions above ground ..... inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|     |      |       |    |
|-----|------|-------|----|
| S23 | R28W | T149N |    |
| NW  | SW   | SE    | NE |

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|                      |                      |                      |       |
|----------------------|----------------------|----------------------|-------|
| T149N<br>R28W<br>S23 | T149N<br>R28W<br>S26 | T149N<br>R28W<br>S26 |       |
| B. T.                | B. T.                | B. T.                | B. T. |

Species spruce  
Diameter 7"  
Bearing N30°W, S10°30'W, S12°W, N61°E  
Distance 8 li., 15 li., 36 li., 15 links


Do you believe this to be a genuine Land Office Corner? yes  
If not, why? .....

*Handwritten Signature:* Harrison Hanna  
(Signature)

12/4/34  
(Date)

Asst. Leader  
(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree ..... inches diameter, on the

side of

from which this Corner bears

..... chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture  
FOREST SERVICE

R-21

*Chippewa Acq* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W S<sup>th</sup> Mer.

Section Corner common to Sections  
23, 24, 26, and 25

Corner consists of a Wood post <sup>Not</sup> in place  
State condition Sound Post

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|    |    |    |    |
|----|----|----|----|
|    |    |    |    |
| NW | SW | SE | NE |

5-23 S R28W T149N  
S- S-

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|                      |                      |                      |    |
|----------------------|----------------------|----------------------|----|
| T149N<br>R28W<br>S23 | 149 N<br>R28W<br>S26 | 149 N<br>R28W<br>S26 |    |
| BT                   | BT                   | BT                   | BT |

Species Spruce Spr Spr Tamarack  
Diameter 6" 7" 9" 5"  
Bearing N70°W S14°30'W S12°W N61°E  
Distance 8.2 li 15 li 36 li 56 li

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_

H. Adams

(Signature)

12/4/34  
(Date)

Chief of Party  
(Title)

R-21

