

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 5P Mer.

Corner common to Sections

11, 12, 13, and 14

Corner consists of a Iron Stake (not) in placeState condition GoodDimensions ^{below} ~~above~~ ground 6" in center of road inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

not
legibleS
11B
M

B.T.

B.T.

—

Species Pine Asb BalmDiameter 10 14 16Bearing S16°W N59W N40EDistance 511ks 911ks 1chDo you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Bearing trees are in bad condition.)Field Man: Hamre by A.C. Norman

(Signature)


Oct. 14, 1935

(Date)

J.F.

(Title)

Corner again.
 Give any further facts which will aid in finding this
 X 6.51245 chains distant.
 from which this Corner bears N 10° E
 side of Tree.
 tree 10 inches diameter, on the NORTH
 Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

T. 149N R. 28W S.P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 28 W. S. 5 P. Mer.
Sec. Corner common to Sections

11, 12, 13, and 14

Corner consists of a Iron stake (~~not~~) in place
State condition Good

Dimensions ~~above~~ below ground 6" in center of Road inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

not legible

S 11

B. T.

--

B. T.

B. T.

-

--

Species Pine Ash Balm

Diameter 10 14 16

Bearing S16W N59W N40E

Distance 51 LKS. 91 LKS. 1 Ch

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Bearing Tree are in bad condition)

Field No. + Home by J. C. Norman

(Signature)


Oct. 14, 1925

(Date)

J. E.

(Title)

Metal Location Poster is on a Balsam tree 10 inches diameter, on the North side of Tree.
 from which this Corner bears N 10° E
 865 11 mms chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 149 N. R. 28 W. 5 P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa Aeg. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 28 W. 5th Mer.

Section Corner common to Sections

11, 12, 14, and 13

Corner ~~consists of a~~ (not) in place
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Sec. 11</u>			
<u>B.T.</u>			

Species Aspen

Diameter 12"

Bearing N50°W

Distance 92.6

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? NO CORNER PRESENT. B.T. SHOWS A 9 E.

H. Adams
(Signature)


Chief of Party
(Title)

12/11/34
(Date)

J 21

Handwritten notes on ruled lines, including "in section of road" and "Corner again."

Give any further facts which will aid in finding this
Corner again.
99 links distant.
from which this Corner bears N 50° W
side of ...
tree 18 inches diameter, on the SE
Metal Location Poster is on a ASPDH



(Make sketch of topography near Corner)

T. 149N. R. 28W. 5th Mer.