

G-25

NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 20 W Mer.

Corner common to Sections  
12, 9, and

Corner consists of a stone (not) in place  
 State condition

Dimensions above ground 4 1/2 x 3 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>12</u>		<u>9</u>
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1</u> <u>4</u> <u>5</u> <u>7</u>			

Species oak

Diameter 12

Bearing S 87 1/2 E

Distance 200

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Date)

(Signature) Ed Miles  
 (Title)

G-25

for Sec. 7 only



Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

103

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W-27W 5th P Mer.  
1/4 Corner common to Sections

12, 7, and  
 Corner consists of a STAKE (not) in place

State condition FAIR

Dimensions above ground 4" x 4" x 30" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>3</u>		<u>5</u>
	<u>12</u>		<u>7</u>
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>37</u>			
<u>BT</u>			

Species Birch

Diameter 12"

Bearing S 87° 15' W

Distance 23 Lks.

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Ed Miller  
 (Signature)

OCT 22 1935  
 (Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

G-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 27 SUP Mer.

1/4 Corner common to Sections  
12, 7, and

Corner consists of a STAKE (not) in place  
State condition FAIR

Dimensions above ground 4X4X30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>S</u>		<u>S</u>
	<u>12</u>		<u>7</u>

N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>			
<u>S7</u>			
<u>BT</u>			

Species BIRCH

Diameter 12"

Bearing S87°15'E

Distance 23 LINKS

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Ed. Miller  
(Signature)

(Title)

OCT 22-35  
(Date)

G-25

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.