

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

✓ 3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 29 W 5th. P. Mer. Quarter

Corner common to Sections

30, and 31

Corner consists of a Cedar post (not) in place


State condition Good

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

New BT

Original BT			
$\frac{1}{4}$ S 31		$\frac{1}{4}$ S 31	
BT		BT	

Species Spruce Spruce

Diameter 18" 6"

Bearing S29°W S15°E

Distance 25 23

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

John A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

6/23/39
 (Date)

Corner again.

Give any further facts which will aid in finding this

0.25 chains distant.

N15°W

from which this Corner bears

side of


Tree

tree 6 inches diameter, on the

N.W.

Spruce

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 N R. 29 W 5th. P. Mer.