

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

T5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 29 W 5th. P. Mer.  
Quarter

Corner common to Sections

29, and 30

Corner consists of a Oak post (not) in place


State condition Good

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BT		New $\frac{1}{4}$ BT	
		S30	
BT		BT	

Species	ElmStp.	Elm
Diameter	8"	3"
Bearing	S53°W	S52°W
Distance	17 $\frac{1}{2}$	17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

John A. Gjelhaug

6/19/39

(Date)

(Signature)  
Jr. Civil Eng.

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


0.17 chains distant.

from which this Corner bears N52°E

side of Tree

tree 3 inches diameter, on the N.E.

Metal Location Poster is on a Blm



(Make sketch of topography near Corner)

T. 149 N. R. 29 W. 5th. P. Mer.