

U. S. Department of Agriculture
FOREST SERVICE

T 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 29 E. 5th Mer.

1/4 Corner common to Sections

28, and 29

Corner consists of a Balsm Post (not) in place



State condition poor

Dimensions above ground 1 1/2' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. Gorman

E. Gorman (Signature)

Enrollee (Title)

12/1/36/ (Date)

Corner again.

Give any further facts which will aid in finding this


44 chains distant.

from which this Corner bears S. 86° E.

side of Tree

tree 5" inches diameter, on the South

Metal Location Poster is on a Tamarack



(Make sketch of topography near Corner)