

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

R 13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 29 W. 5th P. Mer.



Section \_\_\_\_\_ Corner common to Sections  
21, 22, 27, and 28

Corner consists of an Ash Post (~~not~~) in place  
 State condition Good

Dimensions above ground 36 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B. Ts. S21	B. Ts. S22		
B. T.	B. T.	B. T.	

Species 1'am. Stp. Tam. Stp. Tam. Stp.  
 Diameter 12" 14" 10"  
 Bearing N. 41° W. N. 44° E. S. 54° E.  
 Distance 13 3 17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Reset Cor. by Gov't Notes 1/29/40

John A. Gjelhaug  
 (Signature)

Jr. Civil Engineer  
 (Title)

1/29/40  
 (Date)

Faint, illegible text on ruled lines, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding this

0.25


chains distant.

from which this Corner bears N. 61° E.

side of tree

tree 5 inches diameter, on the N. E.

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 148 N. R. 29 W. 5th P. Mer.