

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

117

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY



T. 149 N R. 29 W 5th P. Mer.
 Section Corner common to Sections
26, 27, 34, and 35

Corner consists of a n Elm Post (~~Rock~~) in place
 State condition Good

Dimensions above ground 36 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Mkd. new B.T.'s

Orig. S27	B.T.'s	T149N R29W S	T149N R29W S
B.T.	B.T.	B.T.	B.T.

Species	<u>Birch</u>	<u>Sp. stump</u>	<u>Spruce</u>	<u>Aspen</u>
Diameter	<u>14"</u>	<u>6"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N50°W</u>	<u>S15°E</u>	<u>N63°E</u>	<u>S16°E</u>
Distance	<u>54</u>	<u>44</u>	<u>69 1/2</u>	<u>49 1/2</u>

Do you believe this to be a genuine Land Office Corner? yes
 If not, why? _____

John A. Gjelhaug

(Signature)

Jr. Civil Engineer


(Title)

1/30/40
 (Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this
0.45 chains distant.
from which this Corner bears S35°E
side of Tree
tree 5 inches diameter, on the S. E.
Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)