

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

52

NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 R. 30 Mer. 5  
30 Corner common to Sections

-----, -----, -----, and -----

Corner consists of a 4' wood post (~~not~~) in place


State condition good condition + I-o-p-p-o

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch -----

Diameter 12" -----

Bearing N15°E -----

Distance 12' -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? No - 306 Section corners

Ralph H. ...  
(Signature)

10-10-47  
(Date)

P. ...  
(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----


Corner again. *For at corner from W.S.*

Give any further facts which will aid in finding this *12 feet* chains distant.

from which this Corner bears *S 15° W* side of

tree *12* inches diameter, on the *SW*

Metal Location Poster is on a *Post*



(Make sketch of topography near Corner)