

U. S. Department of Agriculture
FOREST SERVICE

83

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th Mer.

Center 1/4 Corner common to Sections

19, and

Corner consists of a ripe & Post (not) in place

State condition Poor

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

C	C	C	C
1/4	1/4	1/4	1/4
S	S	S	S
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C 1/4 S			
BT			

Species Basswood

Diameter 11"

Bearing N.45°W.

Distance 4 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. Gorman

E. Gorman

(Signature)

Enrollee

(Title)

4/15/36

(Date)

Corner again.
Give any further facts which will aid in finding this

chains distant.


4

from which this Corner bears

side of Tree

tree 11 inches diameter, on the SE

Metal Location Poster is on a Basswood tree



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th Mer.