

## U. S. Department of Agriculture

FOREST SERVICE

2-9

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th. P. Mer.

Section Corner common to Sections

South, 32, and 33

Corner consists of a Cedar Post (33) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.t.			
S. 32			
B.T.			

Species Tam'c. Down

Diameter 14"

Bearing N. 12° W.

Distance 48

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John A. Gjelhaug  
(Signature)12/1/39  
(Date)Jr. Civil Eng.  
(Title)

2-9

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.73

from which this Corner bears South

side of Tree

tree 12 inches diameter, on the South

Metal Location Poster is on a 'Jam'o.



(Make sketch of topography near Corner)

T. 149 N. R. 50 W. 5th. P. Mer.