

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

X 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th. P. Mer.
Quarter Corner common to Sections

32, and 33

Corner consists of a Tam's. Post in place

State condition Good

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B. Ts.



B. T.

B. T.



Species Tam's. Tam's.

Diameter 6" 6"

Bearing N. 8° E. N. 38° W.

Distance 31 26

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. Hoard


(Signature)

12/5/39
(Date)

Compass Man
(Title)

Corner again.
Give any further facts which will aid in finding this

0.18 chains distant.
from which this Corner bears N. 35° W.
side of Tree
tree 6 inches diameter, on the N.W.
Metal Location Poster is on a Tangle.



(Make sketch of topography near Corner)