

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

213

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th. P. Mer.

South Section Corner common to Sections

34 148-30 & 33, and 34-149-30.

Corner consists of a Sec. Line Post in place


State condition Good

Dimensions above ground 50 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

John A. Gjelhaug

(Signature)

12/5/39
(Date)

Jr. Civil Eng.

(Title)


V

Corner again.
 Re-established from County notes in Orig. place. From county B.T.S. and corner 4.11
 Chas. East.

Give any further facts which will aid in finding this
 chains distant.

from which this Corner bears
 side of Post Set in Orig. Place of Corner.

Metal Location Poster is on a Cedar Sec. Line Post
 tree 6 inches diameter, on the South



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th P. Mer.