

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

X13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th. P. Mer.
Quarter Corner common to Sections

33, and 34

Corner consists of a in Center of Road in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Co. B. T.			
-----------	--	--	--

B. T.			
-------	--	--	--

Species Tam's Stp.

Diameter 10"

Bearing S. 64° E.

Distance 60 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John A. Gjelhaug

(Signature)


11/3/39.

(Date)

Jr. Civil Eng.

(Title)

Corner again.
 Give any further facts which will aid in finding this
 from which this Corner bears **N. 61° 30' W.**
 side of **Tree**
 tree **5** inches diameter, on the **N.W.**
 Metal Location Poster is on an **Aspen**



(Make sketch of topography near Corner)

T 149 N. R. 30 W. 5th. P. Mer.