

U. S. Department of Agriculture

submitted L. S. FOREST SERVICE

X 15

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 31 5th Mer.

C. 1/4 cor. Corner common to Sections

and 24

Corner consists of a spruce () in place

State condition good

Dimensions above ground 2x2x48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

C E N T R E 134	1/4	5	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S C			
BT	BT		

Species *Taxus canadensis*

Diameter 6" 10"

Bearing S 40° W N 37° W

Distance 42 ch 17 ch

Do you believe this to be a genuine Land Office Corner?

If not, why?

E. Bowman

(Signature)

4/13/36

(Date)

CCC

(Title)

