

U. S. Department of Agriculture

FOREST SERVICE

R 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th P. Mer.

Quarter Corner common to Sections

23, and 26

Corner consists of a Wood Post (not) in place


State condition Scribed. poor

Dimensions above ground 24 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Bal. Bal.

Diameter 7" 5"

Bearing S. 74° W. S. 42° W.

Distance 72 97

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

K. V. Styler

(Signature)

Leader


4/25/38

(Date)

(Title)

(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th P. Mer.



Metal Location Poster is on a

Balsam

tree 7 inches diameter, on the

East

side of

Tree

from which this Corner bears

N. 74° E.

chains distant

0.72

Give any further facts which will aid in finding this

Corner again.