

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

N 21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 30 W 5th. P. Mer.  
Section

Corner common to Sections  
13, 14, 23, and 24

Corner consists of a Aspen Hub (~~rock~~) in place

State condition Good

Dimensions above ground flush with road inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

New BT S 14			
BT			

Species Elm  
Diameter 30"  
Bearing N55°W  
Distance 50

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_

John A. Gjelhaug

(Signature)

Jr. Civil Eng

(Title)

5/20/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.50

from which this Corner bears


S55° E

side of

Tree

tree 30" inches diameter, on the S.E.

Metal Location Poster is on a B.M.



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th. P. Mer.