

Form 874-8—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

✓ 25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th. P. Mer.

Section 25, 26, 35, 36 Corner common to Sections
25 and 36
30 & 31 T 149 R 29 W post ~~post~~ in place

State condition Good

Dimensions above ground 48 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T. W.



BT	BT	BT	
----	----	----	--

Species Spl. Stp. Sp. Stp. Sp. Stp.

Diameter 8" 6" 12"

Bearing N59°W N52°E S62°E

Distance 17 17 12

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

John A. Gjelhaug

(Signature)

5/19/39

(Date)

Jr. Civil Eng.

(Title)

~~19~~ 19
 N 3 1/2 E S 6 2 E S 6 1/2 W S 6 1/2 W
 5 5 5 5
 Space Space Space Space
 Orig. B.T. notes

Corner again.

Give any further facts which will aid in finding this

0.04 chains distant.


from which this Corner bears S 25° E

side of

Tree

tree 8 inches diameter, on the S. E.

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 149 N R. 180 W 5th. P. Mer.