

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

13

NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 149 R. 31 Mer.



Corner common to Sections  
31, Central, and Section

Corner consists of a stone in place  
 State condition poor

Dimensions above ground 2 1/2 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Bl. Spr. W. Spr.  
 Diameter \_\_\_\_\_  
 Bearing 100° 310°  
 Distance 16" 32'

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Signature)


(Date)

(Title)

X-3

Corner again.  
Give any further facts which will aid in finding this

3 feet  
from which this Corner bears East  
side of *Street road - 2 in paper*  
tree 4 inches diameter, on the *West*  
Metal Location Poster is on a *Post*



(Make sketch of topography near Corner)