

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

W-21  
W21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 31 W. 5th Mer.

#7-1/16 Corner common to Sections  
35, and 36


Corner consists of a Elm Post (not) in place  
State condition Fair

Dimensions above ground 3 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Basswood Elm

Diameter 11" 9"

Bearing S. 25° E. S. 81° E.

Distance 10 lks. 27 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*E. Gorman*

E. Gorman

(Signature)

Enrollee

(Title)

11/13/36


(Date)

W-21

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

Corner sets 10 lks. east of toping road.



(Make sketch of topography near Corner)