

U. S. Department of Agriculture  
FOREST SERVICE

R-21

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 150 R. 25 Mer. 5

Corner common to Sections 24, 25, 26, and 23.

Corner consists of a POST (not) in place  
State condition


Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species BALSAM Birch BALSAM  
Diameter 14 16 12  
Bearing 45° E N 45° W N  
Distance 25 L 15 L 15 L

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Smith  
(Signature)

10/8-35  
(Date)

(Title)

Corner again.  
W N 2 1/2 E To 400 FT


Give any further facts which will aid in finding this

207 chains distant.

from which this Corner bears 15° NE

side of 1000

tree 9 inches diameter, on the SW side of BALSM  
Metal Location Poster is on a BALSM



(Make sketch of topography near Corner)