

U. S. Department of Agriculture
FOREST SERVICE

R-23

Hipperson NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 25 S. 5 Mer.

1/4 Corner common to Sections
24, and 25


Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Dead Ash

Diameter 12"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Smith
(Signature)

10-8-35
(Date)

(Title)

Corner again.
 UNABLE TO LOCATE
 POST - Bearings tree
 ALSO IN FOOT CO. NADITION
 SOME SCROLL MATTERS
 STILL REMAIN

Give any further facts which will aid in finding this
 chains distant.
 257
 from which this Corner bears 200° SE
 side of tree
 tree 4 inches diameter, on the NE
 Metal Location Poster is on a ASH TREE



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

R-23
Posted
4-15-36

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 150N R. 25W 5th Mer.


1/4 Corner common to Sections
24, and 25

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Dead Ash

Diameter 12"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

V. Smith
(Signature)

Compassman
(Title)

10/8/35
(Date)

Unable to locate post,
Bearing tree in poor condition,
some screw markings still remain.

Corner again.


Give any further facts which will aid in finding this

from which this Corner bears $520^{\circ} E$
links chains distant.

side of tree

tree 6 inches diameter, on the NE

Metal Location Poster is on a Ash tree



(Make sketch of topography near Corner)

T. 150 N. R. 25 W. 5th Mer. R-23

U. S. Department of Agriculture

FOREST SERVICE

R23

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 25 W 5th Mer.

1/4 Corner common to Sections
 _____, _____, 24, and 25

Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

Species Dead Ash _____Diameter 12" _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

V. Smith

(Signature)


Compassman

(Title)

10/8/35
(Date)

Corner again.
Unable to locate post.
Bearing tree in poor condition,
some scroll marks, still remains.

Give any further facts which will aid in finding this
Corner bears 520° E
175' chains distant.
25
side of tree
from which this
Metal Location Poster is on a Ask tree
tree 6 inches diameter, on the NE



(Make sketch of topography near Corner)

T. 150 N R. 25 W
5th Mer.
R-23