

U. S. Department of Agriculture

FOREST SERVICE

V-9

RS  
RP

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 150 N. R. 26 W. 5th Mer.

Section 17 Corner common to Sections  
28, 29, 32, and 33

Corner consists of a Pine Post (not) in place  
State condition Good

Dimensions above ground 40 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig

--

BTs

--

--

Mkd. New B.T.

S 28
---------

BT
----

--

--

BT
----

Species J.P. Stp. J.P. Stp. N. Pine

Diameter 10" 10" 12"

Bearing S26°E N4°W N25°E

Distance 9 10 118

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug (Copied)

(Signature)

Jr. Civil Eng.

(Title)

1/10/36  
(Date)

V-9

Corner again.

Give any further facts which will aid in finding this


1.18 chains distant.

from which this Corner bears S 25° W

side of Tree

tree 12 inches diameter, on the SW

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 150 N. R. 26 W. 5-24 Mer.