

U. S. Department of Agriculture

FOREST SERVICE

5.0

59

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 26 Mer.

Corner common to Sections

8, 9, 16, and 17

Corner consists of a Post (not) in place

State condition Good

Dimensions above ground 37 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

8	13	16	9
---	----	----	---

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. S. Hermon

(Signature)

1-4-34

(Date)

Engineer

(Title)

J-9

.....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....

of Road.

Post offset from center

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a Corner Post



(Make sketch of topography near Corner)