

U. S. Department of Agriculture

FOREST SERVICE

P

V-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 26 W 5th Mer.

Section Corner common to Sections

27, 28, 33, and 34

Corner consists of a Ash Post (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|    |    |    |    |
|----|----|----|----|
|    |    |    |    |
| NW | SW | SE | NE |

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

New BT  
by County  
No Scribe  
Marks

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

Species Ash

Diameter 5"

Bearing N 13° E

Distance 7

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug (Copied)


(Signature)

Jr. Civil Eng.

(Title)

V-13

1/10/36  
(Date)



(Make sketch of topography near Corner)

T. 150 N. R. 26 W. 5th Mer.

Metal Location Poster is on a *Ash* tree *5* inches diameter, on the *South* side of *tree* from which this Corner bears *S 13° W* *0.07* chains distant.

Give any further facts which will aid in finding this Corner again.

*Old scribed post orig. Bts lost. Post is in line with old orig. line blazes E + W + S.*