

U. S. Department of Agriculture

FOREST SERVICE

Z-18

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>149</sup>150 R. 26 5TH Mer.

W 1/4

Corner common to Sections

2, and 35

Corner consists of a BALSAM (not) in place

State condition FAIR.

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

NO SCRIBE			
N	W	S	E

CORNER PLACE IN PRESENT SURVEY			
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16			

Species J.P.

Diameter 13"

Bearing N 61° E

Distance 6.1 K

Do you believe this to be a genuine Land Office Corner? No

If not, why? CORNER SET IN PRESENT SURVEY B.T. FROM COUNTY SURVEY

H.C. Norman

(Signature)

DEC. 2, 1935

(Date)

J. Forester

(Title)

Z-18

CORNER ON EDGE OF  
TIMBER

Corner again.

Give any further facts which will aid in finding this


D. 47 chains distant.

From which this Corner bears N 86° W

side of TREE

6 inches diameter, on the NW

Metal Location Poster is on a N.P.



(Make sketch of topography near Corner)

T. 149 R. 26 5TH Mer.