

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N23
P

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N. R. 26 W. 5th P. Mer.

1/4 Corner common to Sections

13, and 24

Corner consists of a WOODEN STAKE (not) in place

State condition Good

Dimensions above ground 3.13 x 3.36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>5</u>		<u>5</u>	
<u>13</u>		<u>24</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>1/4</u>		
<u>S 13</u>	<u>S 13</u>		
<u>BT</u>	<u>BT</u>		

Species SPRUCE BALSAM

Diameter 10 IN. 6 IN.

Bearing N 6 1/2° W. N 32 1/2° E

Distance 47 CNS. 62 CNS.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? RESURVEY BY COUNTY

ENGINEER

Ralph K. Johnson
(Signature)

JULY 17, 1935


(Date)

FOREMAN, C.R.M. 54-7

(Title)

T. 150 N R. 26 W 5TH P. Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a SPRUCE
tree 10 inches diameter, on the SE
side of TRAIL
from which this Corner bears S 6 1/2° E
67 chains distant.

Give any further facts which will aid in finding this
Corner again.

CORNER LOCATION ON
PROPOSED ROAD CENTER LINE

100 W 500 N

CHITEN