

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST T-5

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 25 Mer.

114

Corner common to Sections

29, and 30

Corner consists of a No COR. (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

F. B. Ames

(Signature)

2-13-34

(Date)

(Title)


T-5

-----  
-----  
-----  
-----  
-----

NO 1/4 COR. FOUND. Tag on  
BIRCH 40. chains N of Sec.  
CORS. 29-36-31-32-150-21

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

Mor  
T-6

T. 150 R. 29

Section Corners

*30-27-29* *15*

T


150

R

27

Mer.

SE



Corner is  
a No Corner

Height \_\_\_\_\_

Dia \_\_\_\_\_

Marked \_\_\_\_\_

BEARING TREES

Marks \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

District \_\_\_\_\_

Metal poster on \_\_\_\_\_

Remarks:

*No 1/4 Cor found. Tag on  
Buck 40. Ch 5 N of Soc  
2015 29-30-31-32 T150-27*

Date

7-13-34

Signed

J. R. [Signature]

*T-5*

