

## U. S. Department of Agriculture

## FOREST SERVICE

Chippewa NATIONAL FOREST J-9

## CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 S Mer.

Sec. Corner common to Sections  
8, 9, 16, and 17

Corner consists of a Post (not) in place

State condition S-8-S-9-S-17-T-150-R-27-W-S-16

Dimensions above ground H. 3' Dia 4" x 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S-8		S-9

Species Dead Spruce Dead Spruce Stumper

Diameter 10" 8"

Bearing N 40° W N 55° E

Distance 12 Lks. 44 Lks.

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

L. H. Johnson

(Signature)

Surveyor

(Title)

1-30-34

(Date)

Post in good condition.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 158 R. 27 S. Mer. 9


Section Corners

59

T 131 N.

R 27

Mer. S



Corner is a Post

Height 3'

Dia 4" x 4"

Marked 58, 59

S 17 T 150 N

R 27 W  
S 10

BEARING TREES

Marks	<u>58</u>	<u>59</u>
Species	<u>Red Spruce</u>	<u>Red Spruce</u>
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>N 45° E</u>	<u>N 55° E</u>
District	<u>131 N.</u>	<u>27 W</u>

Metal poster on Spikes - B.T.

Remarks: Post in good condition

Date Jan. 30 Signed Clive W. ...

59

